

FIG. 1A




FIG. 1B




FIG. 1C





FIG. 1D








FIG. 2B




FIG. 2C






FIG. 2D











FIG. 5












FIG. 7







FIG. 8








FIG. 9B




FIG. 9C





FIG. 9D








FIG. 10B




FIG. 10C




FIG. 10D






FIG. 11A



FIG. 11B




FIG. 11C

FIG. 11D




FIG. 11E






FIG. 12A




FIG. 12B




FIG. 12C




FIG. 12D



FIG. 12E





FIG. 12F








FIG. 13B




FIG. 13C

1111

1109

FIG. 13D




FIG. 14A




FIG. 14B




FIG. 14C






FIG. 15






FIG. 16A




FIG. 16B







FIG. 17










FIG. 19A




FIG. 19B






FIG. 20







FIG. 21










FIG. 23







FIG. 24



Ar50cc5uA80kV

4.1

. 0E-04-. 0E-05-. 0E-06-. 0E-07-. 0E-08-. 0E-09 I. 0E-10-

. 0E-03-

. 0E-01-. 0E-02

7.0

Z

3

VD step number

VD start VD step

PARAMETER OF MEASUREMENT

SemiAuto

Comment


FILE NAME CHNSA311

Lot No.:

AP005\_CN

FIG. 25

AP005-17, Unit. S XA3 Y11 ([C], N-ch, L/W=7/8, Tox=115)




-15

. 0E-11-

. 0E-12-




Ar dope 80kV 5E15 (into GI900 A/poly-Si500 A/SiON + SiNO/#1737)



- 6HOUR
- → 8HOUR




Ar dope 80kV 5E15 (into GI900 A/poly-Si500 A/SiON + SiNO/#1737)



- ---- 4HOUR 30μm
  - 6HOUR
- → 8HOUR







■. ロ: 50μm

•. o: 30μm



FIG. 29












FIG. 32






FIG. 33A




FIG. 33B




FIG. 33C




FIG. 33D




FIG. 33E





FIG. 33F






FIG. 34C







FIG. 34D














FIG. 36

	GETTERING CONDITION
MAGNIFICATION	550° C4hrs
X 200	